Estimate Reviews

List of common Pay Item related errors found during Phase submittal reviews to help reduce avoidable ERC comments

Pay Items

Common errors and omissions

FDM 300 Series Only

- 1. Summary Boxes / Summary of Pay Items (SOPI)
 - a. Summary Boxes ordered incorrectly
 - b. Summary Boxes formatted incorrectly
 - c. Required information missing (columns blank that must be filled out)
 - d. LS Pay Items incorrectly shown (units/secondary units, quantities shown, use of design notes column, etc.)
 - e. Pay Items shown in incorrect Summary Boxes
 - f. Pay Items missing from Summary Boxes (shown in SOPI only)
 - g. Pay Items loaded into incorrect category (SOPI)
 - h. Inconsistent quantities between SOPI vs. Summary Boxes/Tabulation of Quantities Tables

FDM 900 Series Only

- 1. Estimated Quantities Report (EQR) / Project Edit Report
 - a. Summary Tables
 - i. Summary Tables ordered incorrectly
 - ii. Summary Tables formatted incorrectly
 - iii. Required information missing (columns blank that must be filled out)
 - iv. LS Pay Items incorrectly shown (units/secondary units, quantities shown, use of design notes column, etc.)
 - v. Pay Items shown in incorrect Summary Tables
 - vi. Pay Items missing from Summary Tables (shown in Project Edit Report only)
 - vii. Pay Items missing from Project Edit Report (shown in Summary Tables only)
 - viii. Pay Items loaded into incorrect category (Project Edit Report)
 - ix. Inconsistent quantities between Project Edit Report vs. Summary Tables/Tabulation of Quantities Tables
 - x. FPIDs not identified on all Summary Tables (when multiple FPIDs)
- 2. Project Edit Report not included in submittal (beginning at Ph II)

9.14.2022 PAGE | **2**

General – FDM 300 & 900 Series

- 1. 999-Do Not Bid Pay Items: Missing/loaded incorrectly
- 2. Plan Notes:
 - a. FDM required General Notes not utilized
 - b. Inappropriate Plan Notes
 - i. Notes attempt to define payment of Contract work items
 - ii. Notes attempt to redefine or restate information already addressed in the FDOT Standard Specifications
- 3. Pay Item Notes:
 - a. Inappropriate Pay Item Notes
 - i. Notes that attempt to "lump" cost of multiple inappropriate Contract Work items with one Pay Item (e.g., "Cost of ABC paid for under Pay Item 123-123)
 - ii. Notes that attempt to define Contractor means and methods
 - b. Sole Source Product Pay Item Note should follow template format used for Turnpike Projects ("123-1-123 will be ACME BRAND MODEL ABC.")
- 4. Improper use of Pay Items with specific requirements to be used (e.g., PI 108-1: Monitor Existing Structures Inspection and Settlement Monitoring)
- 5. Improper use of Pay Items requiring approval
- 6. Improper use of Project Specific Pay Items (using a pay item number that was opened for a different FPID)
- 7. Temporary Traffic Control General Notes still reference FHP and/or Troop K (no longer applicable, must be removed)

9.14.2022 PAGE | **3**